General Purpose Probe Interface

Operating Note/August 1987




Figure 1. HP 10269C General Purpose Probe Interface

Introduction

The HP 10269C General Purpose Probe Interface provides a convenient method of connecting the HP 1650A, HP 1651A, and HP 16510A logic analyzers to digital systems through dedicated interface cards. These dedicated interface cards (preprocessors) allow you to define which system signals are supplied to the analyzer. Refer to Appendix A for the specifications of the HP 10269C.

Operating Note Part Number 10269-90910 Microfiche Part Number 10269-90810

Table of Contents

		_
	Introduction Connecting to Systems Installation General Description Slow Clock HP 10269C Pod Connector Pin-Outs	. 3 . 3 . 5 . 6
Appendix A:	General Information Specifications Replaceable Parts	. 9 . 9
Appendix B:	HP 10269C Signal Routing Signal Routing from Pod Connectors Signal Routing from Ribbon Cables HP 10269C Connector Pin-Outs	15
Appendix C:	Wiring Changes for the HP 10304B	
	Introduction	20

Connecting to Systems

The HP 10269C has two 60-pin connectors which allow connection to dedicated interface cards (ordered separately). A variety of connectors and cables are available for connecting directly to your system.

The HP 1650A, HP 1651A, and HP 16510A logic analyzer probes plug directly into connectors on the HP 10269C Interface. This eliminates the need for individual probe lead connectors.

For specific connections see the documentation that is shipped with each of the dedicated interface cards (preprocessors).

Installation

A dedicated interface card is installed on the underside of the HP 10269C General Purpose Probe Interface and connected to it by two internal cables (see figure 2). Ribbon cables from the interface card connect the general purpose probe interface to your target system. For more specific instructions see the documentation supplied with each of the dedicated interface cards.

Connect the probe pods from the logic analyzer to the pod sockets on the general purpose probe interface. These sockets are labeled pod 1 through 5 as shown in figure 1.




Figure 2. Installing an Interface Card in the HP 10269C

General Description

The HP 10269C General Purpose Probe Interface is a versatile device. With an interface card installed, it provides a flexible and convenient way to probe your target system with the HP 1650A, HP 1651A, and HP 16510A logic analyzers. The software supplied on the flexible disc with the interface card or preprocessor contains setups for the Format and Trace Specification menus (where applicable). It also contains an inverse assembler routine that allows the logic analyzer to display microprocessor data in the assembly language of the corresponding microprocessor.

Microprocessor-specific interface modules, with corresponding software (on flexible discs) are available for many of the most popular microprocessors. You can use these interface modules to quickly probe the 8-bit, 16-bit, or 32-bit microprocessor target system or target system bus of your choice.

These microprocessor-specific interface modules often contain buffers and gating circuits. The buffers supply address, data, clock, and status signals from the target system to the pod connectors on the general purpose probe. For detailed descriptions of these interface modules, refer to the documentation supplied with each interface card or module.

A user definable interface module is also available. It can be configured through a wirewrap interface to specific test ports in your system, or tailored to a specific configuration for a custom microprocessor.

Slow Clock

If you have the interface module hooked up and running and observe a slow clock or no activity on any pods of the interface board, check the +5 V supply coming from the analyzer. To do this:

- Disconnect one of the logic analyzer cables from the HP 10269C and measure across pins 1 and 2 (see figure 3).
 - * If +5 V isn't observed across these pins, check the internal preprocessor fuse on the HP 1650A, HP 1651A, or HP 16510A Logic Analyzer. For information on checking this fuse, refer to the HP 1650A/51A or HP 16510A service manuals.
 - * If +5 V is observed across these pins and you feel confident that the +5 V is getting to the interface module, then the interface module is most likely the problem. If this is the case, contact your nearest Hewlett-Packard Sales/Service Office for information on servicing the board.




Figure 3. Pinout for the Logic Analyzer Cable

HP 10269C Pod Connector Pin-Outs

The HP 10269C acts as a terminator for the HP 1650A, HP 1651A, and HP 16510A logic analyzer probes. It also routes the +5 V power from the logic analyzer probes to the microprocessor interface modules. All of this is accomplished through the five 40-pin connectors on the top of the HP 10269C. Table 1 lists the pin-outs for the odd pins of the five connectors. Figure 4 shows the pin-out for the pod connectors.

Pin	Function	Pin	Function
1	+5 V Power	21	Ch. 8
3	N/C	23	Ch. 7
5	CLK	25	Ch. 6
7	Ch. 15	27	Ch. 5
9	Ch. 14	29	Ch. 4
11	Ch. 13	31	Ch. 3
13	Ch. 12	33	Ch. 2
15	Ch. 11	35	Ch. 1
17	Ch. 10	37	Ch. 0
19	Ch. 9	39	+5 V Power

Table 1. Pin-Outs for Pods 1 through 5

N/C = No connection

Note

Pins 2 and 40 are grounds for the +5 volt power. All the other even-numbered pins are signal grounds.




Figure 4. Pin-Outs for the HP 10269C Pods

A termination network is associated with each clock and data channel on the logic analyzer probe. Figure 5 shows the network used in the HP 10269C.




Figure 5. Termination Network for the Clock and Data Channels

A

General Information

Specifications

Input Connectors:

Two 60-pin connectors to the dedicated

interface card.

Output Connectors:

Five data connectors for logic analyzer

probes.

Instrument

Capability:

HP 1650A, HP 1651A, or HP 16510A

logic analyzers.

Weight:

0.65 kg (1.45 lb)

Dimensions:


See figure A-1.

Replaceable Parts

Replaceable parts for the HP 10269C are shown in table A-1. When ordering a part, address the order to the nearest Hewlett-Packard Sales/Service Office. Include the HP model number of the probe and a complete description of the part, including the HP part number.

Table A-1. HP 10269C Replaceable Parts

Part Number	Description	Quantity
0403-0179	Plastic Bumper	4
10269-04102	Bottom Cover	1
10269-04113	Top Cover	1
10269-66503	Interface Board	1
10269-90910	Op Note Manual	1
10269-94302	Ident. Label	1
10269-94303	Blank Label	1
2200-0107	MS 4-40 0.376LG	4
2200-0512	Screw 4-40 0.312 LG	8
2200-0762	MS 4-40 0.250 LG	2
5951-1125	Label (Serial No.)	1
64232-60201	Endcap Assembly	2



Note

The dimensions in figure A-1 are displayed in millimetres and (inches).

B

HP 10269C Signal Routing

Signal Routing from Pod Connectors

Table B-1 shows how the signals are routed from the pod connectors on the top of the HP 10269C to the ribbon cables that connect to the interface modules.

Table B-1. HP 10269C Signal Routing

Pod	Connector	Ribbon	Cable
Pod	Channel	Cable	Pin
1 1 1 1 1 1 1	0 1 2 3 4 5 6 7	J3 J3 J3 J3 J3 J3 J3	45 46 47 48 49 50 51
1 1 1 1 1 1 1 1	8 9 10 11 12 13 14 15 J CLK	J3 J3 J3 J3 J3 J3 J3 J3	53 54 55 56 57 58 59 60 23

Table B-1. HP 10269C Signal Routing (Continued)

			`
Pod	Connector	Ribbon	Cable
Pod	Channel	Cable	Pin
2	0	J4	1
	1	J4	2
2	2	J4	3
2 2 2 2 2 2 2	3	J4	2 3 4
2	4	J4	5
2	5	J4	5 6
2	6	J4	7
2	7	J4	8
_			
2	8	J4	9
2	9	J4	10
2	10	J4	13
2	11	J4	14
2	12	J4	15
2	13	J4	16
2	14	J4	17
2	15	J4	18
2 2 2 2 2 2 2 2 2 2	K CLK	J3	21
_			
3	0	J4	19
3	1	J4	20
3	. 2	J4	21
3	3	J4	22
3 3 3 3 3 3	4	J3	41
3	5	J3	42
3	6	J3	43
3	7	J3	44
1	1	1	

Table B-1. HP 10269C Signal Routing (Continued)

Pod Connector		Ribbon	Cable
Pod	d Channel Cat		Pin
3	8	J4	39
3	9	J4	40
3 3 3 3 3 3 3 3 3	10	J4	41
3	11	J4	42
3	12	J4	43
3	13	J4	44
3	14	J4	45
3	15	J4	46
3	L CLK	J3	17
4	0	J4	58
4	1	J4	59
4	2	J4	60
4	2 3 4	J3	1
4	4	J3	2 3
4	5	J3	3
4	6	J3	4
4	7	J3	6
4	8	J3	8
4	9	J3	15
4	10	J3	24
4	11	J3	25
4	12	J3	26
4	13	J3	27
4	14	J3	28
4	15	J3	29
4	M CLK	J3	19

Table B-1. HP 10269C Signal Routing (Continued)

Pod Connector		Ribbon	Cable
Pod	Channel	Channel Cable P	
5	0	J3	30
5	1	J3	31
5	2	J3	32
5	3	J3	33
5	4	J3	34
5	5	J3	35
5	6	J3	36
5	7	J3	37
5	8	J4	47
5	9	J4	48
5	10	J4	51
5	11	J4	52
5	12	J4	
5	13	J4	54
5	14	J4	55
5	15	J4	56
5	N CLK	J3	11

The following pins are not connected:

Signal grounds are on:

Note

Power for the interface modules comes from the logic analyzer and is routed through pins 11, 12, 23, and 24 of ribbon cable J4. The return path for power is pins 25 through 28, 37, and 38 of ribbon cable J4.

^{*} Cable J3 pins 5, 7, 9, 10, 12, 16, 18, 20 and 22; and

^{*} Cable J4 pins 49, 50, and 57.

^{*} Cable J3 pins 13, 14, and 38 through 40; and

^{*} Cable J4 pins 29 through 36.

Signal Routing from Ribbon Cables

Table B-2 shows the signal routing from ribbon cable connectors J3 and J4 to the pods on the top of the HP 10269C. This is the same information that is presented in table B-1, except that it has been rearranged for your convenience.

Table B-2. HP 10269C Signal Routing

Cable J3	Pod	Connector	Cable J4	Pod (Connector
Pin	Pod	Channel	Pin	Pod	Channel
1 2 3 4 5 6 7	4 4 4 N/C	3 4 5 6	1 2 3 4 5 6 7	2 2 2 2 2	0 1 2 3 4
7 8 9 10	N/C 4 N/C N/C	8	7 8 9 10	2 2 2 2 2	6 7 8 9
11 12 13 14 15	5 N/C SIG GND SIG GND 4	N CLK	11 12 13 14 15	+5 VDC +5 VDC 2 2 2	10 11 12
16 17 18 19 20	N/C 3 N/C 4 N/C	L CLK	16 17 18 19 20	2 2 2 3 3	13 14 15 0 1

N/C = No connection

Table B-2. HP 10269C Signal Routing (Continued)

Cable J3	Pod C	onnector	Cable J4	Pod (Connector
Pin	Pod	Channel	Pin	Pod	Channel
21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40	2 N/C 1 4 4 4 4 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	K CLK J CLK 10 11 12 13 14 15 0 1 2 3 4 5	21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40	3 +5 VDC +5 VDC PWR GND PWR GND PWR GND SIG GND	2 3

N/C = No connection

Table B-2. HP 10269C Signal Routing (Continued)

Cable J3	Pod (Connector	Cable J4	Pod (Connector
Pin	Pod	Channel	Pin	Pod	Channel
41 42 43 44 45	3 3 3 1	4 5 6 7 0	41 42 43 44 45	3 3 3 3	10 11 12 13 14
47 48 49 50	1 1 1 1	2 3 4 5	47 48 49 50	3 5 5 N/C N/C	8 9
51 52 53 54 55	1 1 1 1	6 7 8 9 10	51 52 53 54 55	5 5 5 5 5	10 11 12 13 14
56 57 58 59 60	1 1 1 1	11 12 13 14 15	56 57 58 59 60	5 N/C 4 4	15 0 1 2

N/C = No connection

HP 10269C Connector Pin-Outs

Figure B-1 shows the pin-outs for the connectors on ribbon cables J3 and J4. Pin 1 is indicated on the connector by a small arrowhead molded into the side of the connector.

Figure B-2 shows the pin-outs for the pod connectors.




Figure B-1. Pin-Out for J3 and J4




Figure B-2. Pin-Outs for the HP 10269C Pods

C

Wiring Changes for the HP 10304B

Introduction

Certain 8085 Preprocessors (HP 10304B) must be updated to work with the HP 1650A, HP 1651A, and HP 16510A logic analyzers. These preprocessors can be easily updated by adding a jumper to re-route a clock signal, which allows the logic analyzer to probe the 8085 with only two logic analyzer probes.

The signal being re-routed is the ALE signal from the 8085. ALE is used as the slave clock for the logic analyzer and is essential for proper operation of the preprocessor.

The boards requiring modification are HP part numbers:

64655-66501

64655-66502

64655-66503

64655-66504

HP part number 64655-66505 doesn't need to be modified.

Updating the **Preprocessor**

To update the preprocessor:

- Remove the printed circuit board from the preprocessor sheet metal.
- Locate pin 1 of the blue 60-pin connector labeled J3. The connector is shown in figure C-1 from the component side of the PC board.




Figure C-1. Component Side of the PC Board

3. Solder a jumper from pin 17 of J3 to pin 21 of J3. Figure C-2 shows the location of the jumper on connector J3 from the circuit side of the PC board.




Figure C-2. Circuit Side of the PC Board

4. Carefully re-assemble the PC board on the preprocessor sheet metal and reconnect any loose hardware.

Note

It may be useful to attach a sticker to the sheet metal of the preprocessor indicating that the preprocessor has been updated.

Additional Information

This hardware modification allows the 8085 preprocessor to work properly with the HP 1650A, HP 1651A, and HP 16510A logic analyzers. The following equipment is also required:

HP Part Number	Description		
10269C	Adapts the 8085 Preprocessor to the HP 1650A/51A and HP 16510A probes		
10304-13015	8085 inverse assembler software for the HP 1650A/51A and HP 16510A logic analyzers		
10304-90910	8085 Operating Note for the HP 1650A/51A and HP 16510A		

Product Warranty

This Hewlett-Packard product has a warranty against defects in material and workmanship for a period of 1 year from date of shipment. During warranty period, Hewlett-Packard Company will, at its option, either repair or replace products that prove to be defective.

For warranty service or repair, this product must be returned to a service facility designed by Hewlett-Packard. However, warranty service for products installed by Hewlett-Packard and certain other products designed by Hewlett-Packard will be performed at Buyer's facility at no charge within the Hewlett-Packard service travel area. Outside Hewlett-Packard service travel areas, warranty service will be performed at Buyer's facility only upon Hewlett-Packard's prior agreement and Buyer shall pay Hewlett-Packard's round trip travel expenses.

For products returned to Hewlett-Packard for warranty service, the Buyer shall prepay shipping charges to Hewlett-Packard and Hewlett-Packard shall pay shipping charges to return the product to the Buyer. However, the Buyer shall pay all shipping charges, duties, and taxes for products returned to Hewlett-Packard from another country.

Hewlett-Packard warrants that its software and firmware designated by Hewlett-Packard for use with an instrument will execute its programming instructions when properly installed on that instrument. Hewlett-Packard does not warrant that the operation of the instrument, software, or firmware will be uninterrupted or error free.

Limitation of Warranty

The foregoing warranty shall not apply to defects resulting from improper or inadequate maintenance by the Buyer, Buyer-supplied software or interfacing, unauthorized modification or misuse, operation outside of the environmental specifications for the product, or improper site preparation or maintenance.

NO OTHER WARRANTY IS EXPRESSED OR IMPLIED,
HEWLETT-PACKARD SPECIFICALLY DISCLAIMS THE IMPLIED
WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A
PARTICULAR PURPOSE.

Exclusive Remedies

THE REMEDIES PROVIDED HEREIN ARE BUYER'S SOLE AND EXCLUSIVE REMEDIES. HEWLETT-PACKARD SHALL NOT BE LIABLE FOR ANY DIRECT, INDIRECT, SPECIAL, INCIDENTAL, OR CONSEQUENTIAL DAMAGES, WHETHER BASED ON CONTRACT, TORT, OR ANY OTHER LEGAL THEORY.

Assistance

Product maintenance agreements and other customer assistance agreements are available for Hewlett-Packard products.

For assistance, contact your nearest Hewlett-Packard Sales and Service Office. Addresses are provided at the back of this operating note.

Certification

Hewlett-Packard Company certifies that this product met its published specifications at the time of shipment from the factory. Hewlett-Packard further certifies that its calibration measurements are traceable to the United States National Bureau of Standards, to the extent allowed by the Bureau's calibration facility, and to the calibration facilities of other International Standards Organization members.

Safety

This product has been designed and tested according to International Safety Requirements. To ensure safe operation and to keep the product safe, the information, cautions, and warnings in this operating note must be headed.

(c) COPYRIGHT HEWLETT-PACKARD COMPANY 1987 ALL RIGHTS RESERVED



PRINTED IN U.S.A.

For more information, call your local HP sales office listed in the telephone directory white pages. Ask for the Electronic Instruments Department. Or write to Hewlett-Packard U.S.A. - P.O. Box 10301, Palo Alto, CA 94303-0890. Europe - P.O. Box 999, 1180 AZ Ainstelveen, The Netherlands. Canada - 6877 Goreway Drive, Mississauga, L4V1M8, Ontario. Japan - Yokogawa-Hewlett-Packard Ltd., 3-29-21, Takaido-Higashi, Suginami-Ku, Tokyo 168. Elsewhere in the world, write to Hewlett-Packard Intercontinental, 3495 Deer Creek Road, Palo Alto, CA 94304.